

DESCRIPTION OF CORNER EVIDENCE FOUND

FOUND GLO BRASS CAP IN MOUND AT FENCE CORNER AT POSITION OF 1/4 CORNER. THE MONUMENT HAD PREVIOUSLY BEEN DISTURBED DURING PIPELINE CONSTRUCTION. RE—SET FROM TIES TAKEN PRIOR TO CONSTRUCTION

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THE CORNER

USED NAIL AND WASHERS, EXISTING STRUCTURES, AND ADJOINING CORNERS AS REFERENCE POINTS AS SHOWN



MARKINGS ON MONUMENT

STATE PLANE COORDINATE DATA

(U.S. SURVEY FEET) NAD83 UTAH CENTRAL ZONE N: 7237735.976 E: 1953448.850 NAVD88 EL: 5737.80'

LATITUDE: 40°11'02.67657" N 110°22'46.35251" W LONGITUDE:

ELLIPSOID HEIGHT: 5681.62'

(GEOID 03 CONUS)

PUBLIC LAND SURVEY SYSTEM GCDB ID NO.

UT300030S0040W0_140200



PHOTO OF MONUMENT FACING NORTH

CERTIFICATION

<u>Jerry D. Allred</u> , Professional Land Surveyor, State of Utah, do hereby certify that I have performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve same

Jerry D. Allred, Professional Land Surveyor Certificate No. 148951 Duchesne County Surveyor

